

United States Patent and Trademark Office

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.	
10/603,487	06/25/2003	Jaime Garcia	JK01493	3134	
28268 75	590 05/09/2006		EXAM	EXAMINER	
THE BLACK & DECKER CORPORATION 701 EAST JOPPA ROAD, TW199			NGUYEN, PHONG H		
	TOWSON, MD 21286			PAPER NUMBER	
			3724		
			DATE MAILED: 05/09/2006		

Please find below and/or attached an Office communication concerning this application or proceeding.

Application/Control Number: 10/603,487

Art Unit: 3724

DETAILED ACTION

Claim Rejections - 35 USC § 112

1. The following is a quotation of the first paragraph of 35 U.S.C. 112:

The specification shall contain a written description of the invention, and of the manner and process of making and using it, in such full, clear, concise, and exact terms as to enable any person skilled in the art to which it pertains, or with which it is most nearly connected, to make and use the same and shall set forth the best mode contemplated by the inventor of carrying out his invention.

2. Claims 50 and 55-58 are rejected under 35 U.S.C. 112, first paragraph, as failing to comply with the enablement requirement. The claim(s) contains subject matter which was not described in the specification in such a way as to enable one skilled in the art to which it pertains, or with which it is most nearly connected, to make and/or use the invention.

Regarding claim 50, it is unclear how the rotatable shaft can move "towards the front portion of the miter base and towards the rear portion".

3. The following is a quotation of the second paragraph of 35 U.S.C. 112:

The specification shall conclude with one or more claims particularly pointing out and distinctly claiming the

subject matter which the applicant regards as his invention.

4. Claim 35 is rejected under 35 U.S.C. 112, second paragraph, as being indefinite for failing to particularly point out and distinctly claim the subject matter which applicant regards as the invention.

Claim 35 recites the limitation "the bevel housing" in line 16. There is insufficient antecedent basis for this limitation in the claim.


Application/Control Number: 10/603,487

Art Unit: 3724

5. The text of those sections of Title 35, U.S. Code not included in this action can be found in a prior Office action.

6. Claim 35 is rejected under 35 U.S.C. 102(b) as being anticipated by Brunson et al. (6.067,885), hereinafter Brunson.

Regarding claim 35, Brunson teaches a miter saw comprising a base, a bevel support 16, a saw assembly, and a bevel lock having a grippable portion 54 having a cam surface 66, a bevel housing and a generally cylindrical shaft 40. See Figs. 4, 5 and 7.



Response to Arguments

7. Applicant's arguments filed 02/21/2006 have been fully considered but they are not persuasive.

Regarding Applicant's argument with respect to claims 50 and 55-58, as shown in Figs. 1, 2, 4 and 6, the shaft 40 is held fixed at both ends by gears 50 and 30, thus, the shaft 40 cannot be pulled toward the front portion of the miter saw.

Regarding Applicant's argument with respect to claim 30, the grip surface is indirectly attached to the base through the shaft 40; and as the saw assembly is pulled down for cutting during a cutting process, the guard is between the bevel lock and the bevel support.

Regarding Applicant's argument with respect to the rotation of the shaft in the paragraph beginning at line 16, since the structure of the shaft and the cam are not positively claimed, the structure of the shaft is interpreted alone, not in the combination of the cam. The shaft in Brunson is constructed to rotate (not in the combination of the pin and the gripping portion) since it has a cylindrical shape; and the shaft is under tension or detention due to the rotation of the cam surface.

Conclusion

8. Any inquiry concerning this communication or earlier communications from the examiner should be directed to Phong H. Nguyen whose telephone number is 571-272-4510. The examiner can normally be reached on Mon-Fri.

Application/Control Number: 10/603,487 Page 5

Art Unit: 3724

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Boyer Ashley can be reached on 571-272-4502. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

DXI.

May 1, 2006

Timothy V. Eley Primary Examiner